This Page Is Inserted by IFW Operations and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.

intentor: David voener, et al. rage i of is





FIGURE 1 - PRIOR ART



Ophical energy
Transmit Lens
Receiving Lens

X(+)

FIGURE 3 - PRIOR ART

Tire 122 Rim 120 Whool Assembly 118

FIGURE 4 - PRIOR ART




FIGURE 5 - PRIOR ART




FIGURE 6 - PRIOR ART




FIGURE 7 - PRIOR ART







FIGURE 8 - PRIOR ART







Inventor: David Voeller, et al. Page 5 of 13



F I G. 12









FIGURE 15



Exp. Mail No. EV 383194804 US - HE 8571 U1

Attorney: Mark E. Books

Reg. No. 40,918




FIGURE 17





FIGURE 18 - PRIOR ART







FIGURE 23 - PRIOR ART

Inventor: David Voeller, et al. Page 9 of 13


METHOD AND APPARATUS FOR VEHICLE SERVICE SYSTEM WITH IMAGING COMPONENTS Exp. Mail No. EV 383194804 US - HE 8571 U1 Reg. No. 40,918

Attorney: Mark E. Books

Inventor: David Voeller, et al. Page 10 of 13




Inventor: David Voeller, et al. Page 11 of 13



400

Inventor: David Voeller, et al. Page 12 of 13







FIGURE 24 - PRIOR ART






FIGURE 26